


Standard Processing and Terminal Protection Treatment

(*: This diagram is for illustrative purposes, so there may be discrepancies from the actual product.)

Process Diagram E (Standard Processing: Air Cap Winding During Bundling)




Process Diagram N (Standard Processing: Unterminated Connector with a Cap)




*There are also cases where only tape is used (without a cap)

Processing Flow P: Pull Termination Process of Unterminated Connector Process Diagram K (Standard Processing: Air Cap Winding During Reeling)



 Process Diagram C (Standard processing suction hose protection for wooden drums)



Processing Flow B: Sunction Hose Protection and Plus Termination Processing

